



LOAD CHARTS AT 633

IDENTIFICATION
AT633

SERIAL NUMBER
45734

REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

Lifting Operations and Lifting
Equipment Regulations 1998
(Regulation 9)

-
1. Customer (and Owner) DALE CRETE
2. Address CAPTAIN BARN FARM
LEEK ROAD
WESTON COYNEY
S-O-T
ST3 5BE
WS8 7JT
- For the Attention of : E
-
3. Address at which the Examination was made. AS ABOVE
4. Description of Lifting Equipment GROVE AT633B TELESCOPING JIB MOBILE HYDRAULIC CRANE
- Distinguishing Number 45734
 - Makers Name GROVE CRANES
 - Year of Manufacture. UNKNOWN
 - Reg. No. F592 WFX
 - Crane Configuration TELESCOPED JIB 4 FALLS HOIST
 - Safe Working Load. 5.80 Tons
 - Boom Length. 10.30 Mtrs
 - Radius. 6.9 Mtrs
5. Nature of Examination. Thorough Examination carried out within an interval of 12 months under Regulation 9(3)(a)(ii) unless otherwise indicated.
6. Identification of any part found to have a defect which is or could become a danger to persons. (see note: 1.) NONE
7. Other defects and remedies.
1. Rear Engine Cows
 2. Upper Accelerator Requires Attention
 3. Upper Cab Door Requires Re-fitting
 4. Upper Cab Seat Requires Re-covering
-

Note 1. State description of the defect and any repair, renewal or alteration required to remedy the defect. Either immediately or within a specified time.

8. Observations and condition of ropes and chains, where applicable particulars of any supplementary test(s).
MAIN HOIST ROPE - GOOD
HOOK BLOCK - FULCRUM SEIZED

Note: Design not checked, this report should be read in conjunction with an EC Declaration of Conformity Certificate and/or Initial Thorough Examination Report (inc load test, where applicable) issued by your manufacturer and /or installer.

9. Date of last Thorough Examination. UNKNOWN
- 9a. Latest date by which the next Thorough Examination must be carried out. 20th August 2020

Unless otherwise stated, this examination has been completed in accordance with LOLER (1998 regulation 9) and BS 121-2:2012
I certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is safe to operate.

Date of Examination: 20th August 2019

Report Date: 20th August 2019


Engineer: W.Lavine

Signature: _____

Crane Engineer to:
Midland Safe Load Indicators Ltd.
Wating Street Works
Wating street,
Brownhills,
West Midlands.
WS8 7JT

Phone: 01543 453166 Fax: 01543 453167 e.mail: midlandsafeload@aol.com

SUPER DASH PANEL ASSEMBLY



- 1 OVERRIDE SWITCH
- 2 AXLE LOCKS
- 3 JACKS