

**RECORD OF THOROUGH EXAMINATION
OF LIFTING PLANT AND EQUIPMENT
IN ACCORDANCE WITH LOLER REGULATIONS 9.3.a****Description of the equipment** (including date of manufacture)

DEMAG AC80/2 MOBILE CRANE 2006

Name and address of owner of equipment, and its location

JAMES KILLELEA LTD STONEHOLME RD BB4 8BA

STOCKPORT

Identification mark of the equipment

81825

VF06CYP

Date of the most recent test and examination or test and thorough examination 20-10-22**and date and number or other identification of the record issued on that occasion** 6730**Date of last thorough examination and number or other identification of the record issued**

10-21 6147

Safe working load or loads and (where relevant) corresponding radii, jib lengths and counterweights

10.80 METRE TO 50 METRE BOOM 2 PART HOIST SWL AS PER DUTY CHART. FLY JIB STOWED

Details of any defects found (if none state NONE)

NONE


Date(s) by which defects described above must be rectified**Any other observations**

OVER HOIST & BOOM ANGLES SATISFACTORY

What parts if any were inaccessible?**(TO BE COMPLETED ONLY AFTER A THOROUGH EXAMINATION OF A HOIST OR LIFT)****Latest date by which the next thorough examination must be carried out** 20-10-23**Declaration**

I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and is found free from any defect likely to affect safety other than those listed above on (date) 20-10-22 and the above particulars are correct.

Signature

**Name and address of person making above declaration (typed or printed)**

Tony Evans

Bradshaw Crane Services

10 Waverley Road

Ellenbrook

Manchester, M28 7UW

Date the record is made 20-10-22